









$d_0$	$\varnothing 10\text{mm}$







**A8**

HUS3-HF 10	$h_{nom}=85\text{mm} \mid t_{fix2}=0\dots 10\text{mm}$
10x100	$t_{fix1} \quad t_{fix1}+t_{fix2}$
10x110	15 mm    15...25 mm
10x110	25 mm    25...35 mm
10x150	65 mm    65...75 mm






$d_0$	$\varnothing 10\text{mm}$	$\varnothing 10\text{mm}$	$\varnothing 8\text{mm}$



**B5**

	$h_{nom1}$	$h_{nom2}$	$h_{nom3}$
HUS3-HF 10	=55mm	=75mm	=85mm
10x60	5 mm	-	-
10x80	25 mm	5 mm	-
10x100	45 mm	25 mm	15 mm
10x110	55 mm	35 mm	25 mm
10x150	95 mm	75 mm	65 mm



		$d_0$
		$\varnothing 10\text{mm}$

